


CORNER RECORD

Document Number 3527-34-94

City of MAMMOTH LAKES

County of MONO, California

Brief Legal Description CENTERLINE MONUMENT MAMMOTH VISTA NO. 3, S. 34, T. 3. S., R. 27E MDRBM



CORNER TYPE

Government Corner ☐ Control ☐
 Meander ☐ Property ☐
 Rancho ☐ Other ☒
 Date of Survey 8-13-98

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FND 2" IRON PIPES ON CENTERLINE @ THE BEGINNING & ENDING OF THE
TANGENT NORTHEAST OF LOT 29 and @ THE BEGINNING OF CURVE NORTHEAST
OF LOT 30 LEADING INTO ABOVE MENTIONED TANGENT. MON'S TIED OUT.

A description of the physical condition of the monument as found and as set or reset: SET 2" PIPES w/ WASHERS
TAGGED "LS4587" AS A DIRECT REPLACEMENT OF FND MON'S AS DESCRIBED ABOVE.
DESTROYED DURING ROAD CONSTRUCTION

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on January 21 19 99.

Signed [Signature] L.S. or R.C.E. Number 4587


COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 1-25 19 99 and examined and filed 1-29 19 99.

Signed [Signature] Title DEPUTY MONO COUNTY SURVEYOR
LIC. EXP. 6-30-00

County Surveyor's Comment _____





LEGEND

- DIRECT REPLACEMENT OF
FND 2" IRON PIPES RCE 15160
DESTROYED DURING ROAD
CONSTRUCTION WITH 2" PK
WASHER "LS4587"

(R) RECORD INFORMATION
PER MB 9/33

BASIS OF BEARING

THE BEARING N 49°48'09"W BETWEEN
TWO FND MONUMENTS ON MAJESTIC
PINES DRIVE.

JN/20